


Sketch of “pull tab” proposal.

To unmate (and maybe to mate?) the connectors without applying force to the kapton / traces / solder connections.



Secure the “posts” into former screw holes in connector body using some epoxy. Of course, done *after* the connector soldering.

*I will perhaps prototype this next week on FST01 module at IU (if Zhenyu says OK?)*

G. Visser IU 11/20/2020