Mirror testing


Jan Vanek 05/19/2025

Overview

- Reference measurement
 - Using Coating 11, mirror 3, before measurement of Coating 37 as a reference and cross-check of test stand setup
- Coating 37

Test measurement

- Reference measurement of Coating 11, mirror 3
- Consistent with previous measurements of the same mirror



Sample 37

Reflectivity measurement of Coating 37

